

BRIDGE INSPECTION REPORT

WO CC WE PD
BAM

Status: Released

Ver Date 4/28/2011

Printed on: 4/28/2011

Agency: Washington State

Program Mgr: Harvey L. Coffman

Bridge No. 162/6

Page 1 of 5

Structure Type CTrus CG

Bridge Name PUYALLUP R

Route 00162

Location 4.4 E JCT SR 410

Structure ID 000000JD

MilePost 6.81

Intersecting PUYALLUP R

Inspector's Signature

FPP

IDent# G0710

Co-Inspector's Signature

WAW

				Inspections Performed:			
5	<input type="text"/>	Structural Adqcy (657)	N	<input type="text"/>	Pier/Abut/Protect (679)	1934	Year Built (332)
2	<input type="text"/>	Deck Geometry (658)	5	<input type="text"/>	Scour (680)	0	Year Rebuilt (336)
9	<input type="text"/>	Underclearance (659)	9	<input type="text"/>	Retaining Walls (682)	F 43	Oper Rating (551)
5	<input type="text"/>	Operating Level (660)	9	<input type="text"/>	Pier Protection (683)	F 26	Inv Rating (554)
8	<input type="text"/>	Alignment Adqcy (661)	0	<input type="text"/>	Bridge Rails (684)	A	Open Close (293)
6	<input type="text"/>	WaterwayAdqcy (662)	0	<input type="text"/>	Transition (685)	9999	Vert Over Deck (360)
7	<input type="text"/>	Deck Overall (663)	1	<input type="text"/>	Guardrails (686)	0000	Vert Under (374)
9	<input type="text"/>	Drains Condition (664)	1	<input type="text"/>	Terminals (687)	N	Vert Und Code (378)
5	<input type="text"/>	Superstructure (671)	N	<input type="text"/>	Revise Rating (688)	3.00	Asphalt Depth
3	<input type="text"/>	Number Utilities (675)		<input type="text"/>	Photos Flag (691)		Design Curb Height
6	<input type="text"/>	Substructure (676)		N	Soundings Flag (693)	50	Speed Limit
8	<input type="text"/>	Chan/Protection (677)		<input type="text"/>	Measure Clearance (694)		
9	<input type="text"/>	Culvert (678)					
							Total: 1.5
							Suff Rating: 46.21 FO 46.21 FO

BRIDGE INSPECTION REPORT

WO CC WE PD
BAM 0 0 0 0

Status: Released

Ver Date 4/28/2011

Printed on: 4/28/2011

Agency: Washington State

Program Mgr: Harvey L. Coffman

Bridge No. 162/6

Page 2 of 5

Structure Type CTrus CG

Bridge Name PUYALLUP R

Route 00162

Location 4.4 E JCT SR 410

Structure ID 000000JD

MilePost 6.81

Intersecting PUYALLUP R

BMS Elements 12 to 801

Element	Element Description	Total	Units	State 1	State 2	State 3	State 4
12	Concrete Deck	4,620	SF	4,620	0	0	0
35	Concrete Deck Soffit	4,620	SF	4,620	0	0	0
110	Concrete Girder	160	LF	160	0	0	0
119	Concrete Truss	340	LF	0	170	170	0
155	Concrete Floor Beam	462	LF	462	0	0	0
202	Steel Pile/Column	5	EA	5	0	0	0
205	Concrete Pile/Column	4	EA	4	0	0	0
212	Concrete Submerged Pier Wall	44	LF	43	0	1	0
215	Concrete Abutment	76	LF	64	0	12	0
264	Timber Sidewalk & Supports	2,730	SF	2,730	0	0	0
311	Moveable Bearing (roller, sliding, etc)	2	EA	2	0	0	0
313	Fixed Bearing	2	EA	2	0	0	0
330	Metal Bridge Railing	80	LF	80	0	0	0
340	Metal Pedestrian Railing	340	LF	290	0	50	0
342	Timber Pedestrian Railing	80	LF	80	0	0	0
361	Scour	2	EA	2	0	0	0
362	Impact Damage	2	EA	1	1	0	0
402	Hot Poured and/or Premolded Joint Filler	44	LF	44	0	0	0
801	AC Overlay with Waterproofing Membrane	4,620	SF	4,620	0	0	0

Notes 0 to 801

0 Orientation is from west to east per route direction. The north and south concrete trusses are double trusses.

12 Covered with an ACP overlay, see element note 801.

35 Diagonal leaching cracks at corners of Spans 1 and 2.

Transverse leaching cracks at Pier 2 where it meets with deck.

There are full width transverse leaching cracks in Span 2 that typically extend into the truss bottom chords.

110 The approach spans have four concrete girder lines each.

Spans 1 and 3 webs of the outside concrete T-beams have several full height hairline leaching cracks that extend into the deck.

BRIDGE INSPECTION REPORT

WO CC- WE PD
BAM

0	0	0	0
---	---	---	---

Status: Released

Ver Date 4/28/2011

Printed on: 4/28/2011

Agency: Washington State

Program Mgr: Harvey L. Coffman

Bridge No. 162/6	Page 3 of 5	Structure Type CTrus CG
Bridge Name PUYALLUP R	Route 00162	Location 4.4 E JCT SR 410
Structure ID 000000JD	MilePost 6.81	Intersecting PUYALLUP R

Notes 0 to 801

119 Span 2 is a concrete truss.

BOTTOM CHORD: The edges have heavy leaching vertical cracks, many of which are rusting. There are a few edge spalls. The chord bottom has several transverse rusty 6" cracks.

Both chords between Floorbeams 2-12 and 2-13 have rock pockets with leached out concrete. The affected areas are approximately 2 ft. x 1 ft. x 1" deep. See photo #17.

The west end of the north chord has a few hoops exposed up to 24" due to lack of cover. Some of the hoops have up to 50 percent section loss.

The west end of the south chord on the bottom has rebars exposed due to lack of cover.

The south bottom chord near Floorbeam 2-4 has two spalls/delaminations about 1 sq. ft. in area.

The south bottom chord near Floorbeam 2-5 has three delaminations totalling about 1.5 sq. ft. in area and an 8" long spall with exposed rebar.

The south bottom chord near Floorbeam 2-15 has four 12" longitudinal rebars exposed due to lack of cover.

TOP CHORD: The outside face at the ends and bottoms have hairline vertical leaching cracks especially bottom of south and north trusses at east portals.

North outside truss member U1-U2 has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #21 and #25.

DIAGONALS AND VERTICALS:

All diagonals have transverse and longitudinal cracks. The diagonal cracks on several members are open up to 1/4" and have delaminated concrete around the edges. Many of the diagonal and vertical member longitudinal cracks and delaminations have been patched.

The verticals are separated by mid-height struts and several of the diagonal bars are exposed on the strut due to lack of cover. This defect is located at U2 and U3 South. See photo #10.

NORTH TRUSS defects noted:

The U2 sidewalk portal on the west side has 8" of exposed rebar due to lack of cover.

The U2-L3 inside diagonal has been patched on top surface. See photo #22. The bottom surface is cracked over the lower half. See photo #23.

The U4 sidewalk portal on the west side has 18" of exposed rebar due to lack of cover in addition to a 12" x 4" delamination. REPAIR 12888.

The L5-U5 outside vertical at the NE corner at the hand rail connection has a 2 ft. x 1 ft. patch. See photo #13.

The L6-U7 inside diagonal on the top face has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #26.

The L7-U8 inside diagonal bottom surface near U8 has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #27.

The L7-U8 outside diagonal bottom surface near U8 has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #28.

The L8-U8 vertical has 18" of exposed rebar on the west face due to lack of cover.

The L8-U9 inside diagonal top surface has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #29.

The L8-U9 outside diagonal on the top face and bottom surface have been repaired. REPAIR #12888 verified 4/4/2011, see Photos #6 and #30.

The L9-U9 inside vertical has a 21" x 8" traffic impact patch along with a 6" x 2" x 1" deep spall.

SOUTH TRUSS defects noted:

The U3-L4 inside diagonal at the top has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #31.

The U3-L4 outside diagonal at the top has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #31.

The L5-U6 inside diagonal at the bottom and the south edge has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #32.

The L6-U7 inside diagonal on the west and south surfaces has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #33.

The L7-U8 inside diagonal at the bottom and east surfaces has been repaired. REPAIR #12888 verified 4/4/2011, see Photo #34.

The L9-U9 vertical has a vertical leaching crack at top of west face that goes into top chord.

155 Span 2 has 21 concrete floorbeams numbered from 2-0 to 2-20. The concrete floorbeams have several exposed rusty stirrups due to lack of cover. Where the floorbeams frame into the bottom chords there are vertical hairline leaching cracks (especially near Floorbeams 2-5 and 2-11).

202 The west abutment cap is undermined and five H-piles are exposed up to 20". Two of the pilings have minor laminar surface rust.

205 The concrete columns have rough and weathered concrete.

BRIDGE INSPECTION REPORT

WO CC- WE PD
BAM 0 0 0 0

Status: Released

Ver Date 4/28/2011

Printed on: 4/28/2011

Agency: Washington State

Program Mgr: Harvey L. Coffman

Bridge No. 162/6 **Page 4 of 5** **Structure Type** CTrus CG
Bridge Name PUYALLUP R **Route** 00162 **Location** 4.4 E JCT SR 410
Structure ID 000000JD **MilePost** 6.81 **Intersecting** PUYALLUP R

Notes 0 to 801

- 212 The Pier 2 and 3 pier walls between the truss columns are wet and moss covered and have a few hairline vertical cracks. The Pier 2 wall on the east face near the top has an 8" diameter x 2-1/2" spall with 4" of exposed rebar. Horizontal leaching cracks at mid-height on west face of Pier 2 wall.
- 215 The west concrete abutment cap is undermined. The east abutment cap has a couple of rock pockets about 4 ft. x 3 ft. in area.
- 264 The approach spans (Spans 1 and 3) have timber girders supporting the sidewalks. The truss span (Span 2) has timber planking that is supported by the truss bottom chord. The timber sidewalk planks are worn, split, and frayed. The approach span girders are wet and mud stained and have green fungus growth in scattered spots.
- 311 The rocker bearings are located at Pier 2. During the 2011 inspection the rockers were in the vertical position.
- 313 The fixed bearing shoes are located at Pier 3.
- 340 Some of the Span 2 pedestrian rail connections have been fixed. However, some are still loose, see Photo #35. REPAIR 12289.
- 342 The timber pedestrian rails are located at Spans 1 and 3. The paint is peeling on the vertical surfaces and missing on the top horizontal surfaces. See photo #18. REPAIR 12286.
- 361 The Puyallup River flows from the south to the north below Span 2. Piers 2 and 3 are considered to be in ordinary high water. Pier 3 has heavy riprap on the stream side.
- 362 The north inside truss has a traffic impact spall at U9. U1south, U2 north and U5 north inside truss traffic spalls have been patched.
- 402 The poured rubber joints are located at Piers 2 and 3.
- 671 The NBI Superstructure code is a '5' due to the spalling, cracking, and delamination of the truss diagonals.
- 675 There is a 16" diameter insulated pipe suspended from the north edge. There is a 5" diameter insulated pipe under the north sidewalk. There is a 6" diameter steel conduit suspended from the south edge.
- 680 This bridge has a pile foundation with greater than 20 ft. of penetration.
- 684 The bridge rails have not been crash tested.
- 685 The transitions are not nested Thrie-beam.
- 693 Soundings done in 2011 from the south rail.
- 801 The AC overlay has ruts in the wheel lines and is cracked transversely over the east abutment.

Repairs 12288 to 12286

Repair	P	R	Repair Description	Date Noted	Verified
12288	1	B	Remove loose concrete from delaminations, clean rusty bars, epoxy coat exposed bars, and patch at the following locations; NORTH TRUSS: Both faces of north outside truss member U1-U2, U4 sidewalk portal westside, L6-U7 inside diagonal top face, L7-U8 inside and outside diagonals bottom surfaces near U8, and L8-U9 inside and outside diagonals top surfaces. SOUTH TRUSS: U3-L4 inside and outside diagonals top surfaces, L5-U6 inside diagonal bottom surface and south edge, L6-U7 inside diagonal west and south surfaces, L7-U8 inside diagonal bottom and east surfaces.	6/25/2009	4/4/2011
12289	1	B	Tighten the Span 2 pedestrian rail anchor screws at the truss vertical connections.	7/15/2009	
12290	1	B	Remove loose concrete from delaminations, clean rusty bars, epoxy coat exposed bars, and patch at the following locations in the North Truss: The U2-L3 member, the bottom surface is cracked over the lower half. The U4 sidewalk portal on the west side has 18" of exposed rebar due to lack of cover.	4/4/2011	
12286	2	B	Paint the approach span pedestrian rails.	5/15/2007	

BRIDGE INSPECTION REPORT

BAM WO CC WE PD
0 0 0 0

Status: Released

Ver Date 4/28/2011

Printed on: 4/28/2011

Agency: Washington State

Program Mgr: Harvey L. Coffman

Bridge No. 162/6

Page 5 of 5

Structure Type CTrus CG

Bridge Name PUYALLUP R

Route 00162

Location 4.4 E JCT SR 410

Structure ID 000000JD

MilePost 6.81

Intersecting PUYALLUP R

Inspections Performed and Resources Required

<u>Report Type</u>	<u>Date</u>	<u>IT</u>	<u>Frg</u>	<u>Hrs</u>	<u>Insp</u>	<u>CertNo</u>	<u>Coinsp</u>	<u>Note</u>
Routine	4/4/2011		24	1.5	FPP	G0710	WAW	

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION
NBI STRUCTURE INVENTORY AND APPRAISAL REPORT (ENGLISH UNITS)

DATE 5/2/2011

IDENTIFICATION			WSBIS DATA		
(1) STATE NAME - WASHINGTON		530	BRIDGE NUMBER		162/6
(8) STRUCTURE NUMBER	# 000000JD0000000		BRIDGE NAME		PUYALLUP R
(5) INVENTORY ROUTE (ON/UNDER) - on		1 3 1 00162	CUSTODIAN		Washington State
(2) HIGHWAY AGENCY DISTRICT		03	CROSSING DESC		PUYALLUP R
(3) COUNTY CODE 53	(4) PLACE CODE 00000		CROSSING KEY		00162 00 00681 00 M Y
(6) FEATURES INTERSECTED		PUYALLUP R	SUFFICIENCY RATING		46.21 FO
(7) FACILITY CARRIED		SR 162	CLASSIFICATION		
(9) LOCATION		4.4 E JCT SR 410	(112) NBIS BRIDGE LENGTH		Y
(11) MILEPOINT		6.81	(104) HIGHWAY SYSTEM - Not on the NHS		0
(12) BASE HIGHWAY NETWORK - Not part of network		0	(26) FUNCTIONAL CLASS - Minor Arterial		16
(13) LRS INV ROUTE AND SUB ROUTE			(100) DEFENSE HIGHWAY - Not a STRAHNET route		0
(16) LATITUDE		47 Deg 7 Min 47.00 Sec	(101) PARALLEL STRUCTURE - Not a parallel bridge		N
(17) LONGITUDE		122 Deg 14 Min 6.00 Sec	(102) DIRECTION OF TRAFFIC - 2-way traffic		2
(98) BORDER BRIDGE STATE CODE - Not a border bridge			(103) TEMPORARY STRUCTURE -		
(99) BORDER BRIDGE STRUCTURE NO			(105) FEDERAL LANDS HIGHWAY - Not Applicable		0
STRUCTURE TYPE AND MATERIAL			(110) DESIGNATED NATIONAL NETWORK - Part of network		1
(43) STRUCTURE TYPE MAIN: MATERIAL - Concrete			(20) TOLL - Non-toll structure		3
DESIGN - Truss - Thru		110	(21) MAINTAIN - State Highway Agency		1
(44) STRUCTURE TYPE APPR: MATERIAL - Concrete			(22) OWNER - State Highway Agency		1
DESIGN - Tee beam		104	(37) HISTORICAL SIGNIFICANCE - On the NRHP		1
(45) NO. OF SPANS IN MAIN UNIT		1	CONDITION		
(46) NO. OF APPROACH SPANS		2	(58) DECK		7
(107) DECK STRUCT TYPE - Conc. CIP		1	(59) SUPERSTRUCTURE		5
(108) WEARING SURFACE / PROTECTIVE SYSTEM:			(60) SUBSTRUCTURE		6
(A) TYPE OF WEARING SURFACE - Bituminous		6	(61) CHANNEL AND CHANNEL PROTECTION		8
(B) TYPE OF MEMBRANE - Preformed fabric		2	(62) CULVERTS		N
(C) TYPE OF DECK PROTECTION - None		0	LOAD RATING AND POSTING		
AGE AND SERVICE			(31) DESIGN LOAD - H 15		2
(27) YEAR BUILT		1934	(63) OPERATING RATING METHOD - Load Factor (LF)		1
(106) YEAR RECONSTRUCTED		0	(64) OPERATING RATING		43 T
(42) TYPE OF SERVICE ON - Highway & Pedestrian		5	(65) INVENTORY RATING METHOD - Load Factor (LF)		1
UNDER - Waterway		5	(66) INVENTORY RATING		26 T
(28) LANES: ON STRUCTURE 2	UNDER STRUCTURE 0		(70) BRIDGE POSTING - Equal or above legal loads		5
(29) AVERAGE DAILY TRAFFIC		18425	(41) STRUCT OPEN, POSTED, CLOSED - Open, no restrictions		A
(30) YEAR OF ADT 2007	(109) TRUCK ADT 10%		APPRAISAL		
(19) BYPASS, DETOUR LENGTH		18.0 mi	(67) STRUCTURAL EVALUATION		5
GEOMETRIC DATA			(68) DECK GEOMETRY		2
(48) LENGTH OF MAXIMUM SPAN		170 ft	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL		N
(49) STRUCTURE LENGTH		210 ft	(71) WATERWAY ADEQUACY		6
(50) CURB OR SIDEWALK: LEFT 6.5 ft	RIGHT 6.5 ft		(72) APPROACH ROADWAY ALIGNMENT		8
(51) BRIDGE ROADWAY WIDTH CURB TO CURB		22.0 ft	(36) TRAFFIC SAFETY FEATURES		0011
(52) DECK WIDTH OUT TO OUT		37.5 ft	(112) SCOUR CRITICAL BRIDGE		5
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)		30 ft	PROPOSED IMPROVEMENTS		
(33) BRIDGE MEDIAN - No median		0	(75) TYPE OF WORK -		311
(34) SKEW 0 Deg	(35) STRUCTURE FLARED no 0		(76) LENGTH OF STRUCTURE IMPROVEMENT		260.0 ft
(10) INVENTORY ROUTE MIN VERT CLEAR			(94) BRIDGE IMPROVEMENT COST		\$4,576,000
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR		22 ft 00 in	(95) ROADWAY IMPROVEMENT COST		\$915,000
(53) MIN VERT CLEAR OVER BRIDGE RDW		99 ft 99 in	(96) TOTAL PROJECT COST		\$9,152,000
(54) MIN VERT UNDERCLEAR		0 ft 00 in	(97) YEAR OF IMPROVEMENT COST ESTIMATE		2010
(55) MIN LAT UNDERCLEAR RT		0.0 ft	(114) FUTURE ADT		27638
(56) MIN LAT UNDERCLEAR LT		0.0 ft	(115) YEAR OF FUTURE ADT		2027
NAVIGATION DATA			INSPECTIONS		
(38) NAVIGATION CONTROL - No nav control		0	(90) INSPECTION DATE 04/11	(91) FREQUENCY 24 MO	
(111) PIER PROTECTION -			(92) CRITICAL FEATURE INSPECTION:	(93) CFI DATE	
(39) NAVIGATION VERTICAL CLEARANCE		0 ft	(A) FRACTURE CRIT DETAIL - NO -	Month (A) _/_	
(116) VERT-LIFT BRIDGE NAV MIN VERT CLR			(B) UNDERWATER INSP - NO -	Month (B) _/_	
(40) NAVIGATION HORIZONTAL CLR		0 ft	(C) OTHER SPECIAL INSP - NO -	Month (C) _/_	